

 D

Е

F

Н

J

L

Ν

0

Р

CONTENTS

PRECAUTION	2
PRECAUTIONS Precaution for Supplemental Restraint System (SRS) "AIR BAG" and "SEAT BELT PRE-TEN- SIONER" Precaution for Procedure without Cowl Top Cover Precaution for Work	2 2
PREPARATION	4
PREPARATION Special Service Tools Commercial Service Tools	4
CLIP LIST Descriptions for Clips	
SYMPTOM DIAGNOSIS	9
SQUEAK AND RATTLE TROUBLE DIAG- NOSES	
Generic Squeak and Rattle Troubleshooting Diagnostic Worksheet	. 11
REMOVAL AND INSTALLATION	.15
FRONT BUMPER Exploded View Removal and Installation	. 15

REAR BUMPER	
Exploded ViewRemoval and Installation	20
Removal and installation	20
FRONT GRILLE	
Exploded View	23
Removal and Installation	23
COWL TOP	24
Exploded View	24
Removal and Installation	24
FENDER PROTECTOR	26
Exploded View	
Removal and Installation	
DOOF OIDE MOI DING	
ROOF SIDE MOLDING	
Exploded ViewRemoval and Installation	
DOOR OUTSIDE MOLDING	
Exploded View	
Removal and Installation	29
TRUNK LID FINISHER	30
Exploded View	
Removal and Installation	30
DOOR PARTING SEAL	31
Exploded View	
Removal and Installation	
REAR SPOILER	22
Exploded View	
Removal and Installation	

PRECAUTION

PRECAUTIONS

Precaution for Supplemental Restraint System (SRS) "AIR BAG" and "SEAT BELT PRE-TENSIONER"

The Supplemental Restraint System such as "AIR BAG" and "SEAT BELT PRE-TENSIONER", used along with a front seat belt, helps to reduce the risk or severity of injury to the driver and front passenger for certain types of collision. This system includes seat belt switch inputs and dual stage front air bag modules. The SRS system uses the seat belt switches to determine the front air bag deployment, and may only deploy one front air bag, depending on the severity of a collision and whether the front occupants are belted or unbelted. Information necessary to service the system safely is included in the SR and SB section of this Service Manual.

WARNING:

- To avoid rendering the SRS inoperative, which could increase the risk of personal injury or death in the event of a collision which would result in air bag inflation, all maintenance must be performed by an authorized NISSAN/INFINITI dealer.
- Improper maintenance, including incorrect removal and installation of the SRS, can lead to personal
 injury caused by unintentional activation of the system. For removal of Spiral Cable and Air Bag
 Module, see the SR section.
- Do not use electrical test equipment on any circuit related to the SRS unless instructed to in this Service Manual. SRS wiring harnesses can be identified by yellow and/or orange harnesses or harness connectors.


PRECAUTIONS WHEN USING POWER TOOLS (AIR OR ELECTRIC) AND HAMMERS

WARNING:

- When working near the Airbag Diagnosis Sensor Unit or other Airbag System sensors with the Ignition ON or engine running, DO NOT use air or electric power tools or strike near the sensor(s) with a hammer. Heavy vibration could activate the sensor(s) and deploy the air bag(s), possibly causing serious injury.
- When using air or electric power tools or hammers, always switch the Ignition OFF, disconnect the battery, and wait at least 3 minutes before performing any service.

Precaution for Procedure without Cowl Top Cover

When performing the procedure after removing cowl top cover, cover the lower end of windshield with urethane, etc to prevent damage to windshield.



Precaution for Work

INFOID:0000000009268543

INFOID:0000000009268542

- When removing or disassembling each component, be careful not to damage or deform it. If a component may be subject to interference, be sure to protect it with a shop cloth.
- When removing (disengaging) components with a screwdriver or similar tool, be sure to wrap the component with a shop cloth or vinyl tape to protect it.
- Protect the removed parts with a shop cloth and prevent them from being dropped.
- Replace a deformed or damaged clip.
- If a part is specified as a non-reusable part, always replace it with a new one.
- Be sure to tighten bolts and nuts securely to the specified torque.
- After installation is complete, be sure to check that each part works properly.
- Follow the steps below to clean components:
- Water soluble dirt:

Revision: April 2013 EXT-2 2014 Versa Sedan

PRECAUTIONS

< PRECAUTION >

- Dip a soft cloth into lukewarm water, wring the water out of the cloth and wipe the dirty area.
- Then rub with a soft, dry cloth.
- Oily dirt:
- Dip a soft cloth into lukewarm water with mild detergent (concentration: within 2 to 3%) and wipe the dirty area.
- Then dip a cloth into fresh water, wring the water out of the cloth and wipe the detergent off.
- Then rub with a soft, dry cloth.
- Do not use organic solvent such as thinner, benzene, alcohol or gasoline.
- For genuine leather seats, use a genuine leather seat cleaner.

Α

В

D

C

Ε

F

G

Н

J

M

Ν

0

Р

PREPARATION

PREPARATION

Special Service Tools

INFOID:0000000009268544

Tool number (Kent-Moore No.) Tool name		Description
— (J-39570) Chassis Ear	SIIA0993E	Locating the noise
— (J-43980) NISSAN Squeak and Rattle Kit	SIIA0994E	Repairing the cause of noise
 (J-46534) Trim Tool Set	AWIIA0483ZZ	Removing trim components

Commercial Service Tools

INFOID:0000000009268545

(Kent-Moore No.) Tool name		Description
(J-39565) Engine Ear	SIIA0995E	Locating the noise
(—) Power tool		Loosening nuts, screws and bolts
	PIIB1407E	

CLIP LIST

Descriptions for Clips

INFOID:0000000009268546

Replace any clips which are damaged during removal or installation.

Symbol No.	Shapes	Removal & Installation
C101		Removal: Remove by bending up with flat-bladed screwdrivers or clip remover.
C103	TTTT	Removal: Remove with a clip remover.
C203 [(7)		Removal: Push center pin to catching position. (Do not remove center pin by hitting it.) Push Push Installation:
C205		Removal: Flat-bladed screwdriver Clip Finisher
C206		Removal:

SIIA0315E

Revision: April 2013 EXT-5 2014 Versa Sedan

С

Α

В

D

Ε

F

G

Н

J

.

M

Ν

0

Р

Symbol No.	Shapes	Removal & Installation
CE103		Removal:
CF110	Clip A	Removal: Finisher Clip A Flat-bladed screwdrivers Clip B
CF118	Clip A Clip B (Grommet)	Removal: Flat-bladed Finisher screwdrivers Body panel Clip A Clip B (Grommet)
CR103		Removal: Holder portion of clip must be spread out to remove rod.
CS101		Removal: 1. Screw out with a Phillips screwdriver. 2. Remove female portion with flat-bladed screwdriver.

SIIA0316E

Symbol No.	Shapes	Removal & Installation
CG101		Removal: Installation: Rotate 45° to remove Removal:
CS102	(X)	
CS113		Removal: Disconnect upper connection of clip with a flat-bladed screwdriver, then remove clip while inserting a flat-bladed screwdriver between body panel and clip.
C111		

SIIA0317E

Α

В

С

D

Е

F

G

Н

J

EXT

L

 \mathbb{N}

Ν

0

Р


Symbol No.	Shapes	Removal & Installation
CG104		Removal: Remove by bending up with flat-bladed screwdrivers. Radiator grille Body panel
CE114		
CF118	Clip A Clip B (Grommet)	Removal: Flat-bladed Finisher screwdrivers Body panel Clip B (Grommet)

ALJIA0564GB

SYMPTOM DIAGNOSIS

SQUEAK AND RATTLE TROUBLE DIAGNOSES

Work Flow



CUSTOMER INTERVIEW

Interview the customer if possible, to determine the conditions that exist when the noise occurs. Use the Diagnostic Worksheet during the interview to document the facts and conditions when the noise occurs and any customer's comments; refer to EXT-13, "Diagnostic Worksheet". This information is necessary to duplicate the conditions that exist when the noise occurs.

- The customer may not be able to provide a detailed description or the location of the noise. Attempt to obtain all the facts and conditions that exist when the noise occurs (or does not occur).
- If there is more than one noise in the vehicle, be sure to diagnose and repair the noise that the customer is concerned about. This can be accomplished by test driving the vehicle with the customer.
- After identifying the type of noise, isolate the noise in terms of its characteristics. The noise characteristics
 are provided so the customer, service adviser and technician are all speaking the same language when
 defining the noise.
- Squeak —(Like tennis shoes on a clean floor)
 Squeak characteristics include the light contact/fast movement/brought on by road conditions/hard surfaces
 higher pitch noise/softer surfaces = lower pitch noises/edge to surface = chirping.
- Creak—(Like walking on an old wooden floor)
 Creak characteristics include firm contact/slow movement/twisting with a rotational movement/pitch dependent on materials/often brought on by activity.
- Rattle—(Like shaking a baby rattle)
 Rattle characteristics include the fast repeated contact/vibration or similar movement/loose parts/missing clip or fastener/incorrect clearance.
- Knock —(Like a knock on a door)
 - Knock characteristics include hollow sounding/sometimes repeating/often brought on by driver action.
- Tick—(Like a clock second hand)
 - Tick characteristics include gentle contacting of light materials/loose components/can be caused by driver action or road conditions.
- Thump—(Heavy, muffled knock noise)
 - Thump characteristics include softer knock/dead sound often brought on by activity.
- Buzz—(Like a bumble bee)
 - Buzz characteristics include high frequency rattle/firm contact.
- Often the degree of acceptable noise level will vary depending upon the person. A noise that you may judge as acceptable may be very irritating to the customer.
- Weather conditions, especially humidity and temperature, may have a great effect on noise level.

DUPLICATE THE NOISE AND TEST DRIVE

<u>E</u>XT

Α

Е

M

N

0

Р

Revision: April 2013 EXT-9 2014 Versa Sedan

< SYMPTOM DIAGNOSIS >

If possible, drive the vehicle with the customer until the noise is duplicated. Note any additional information on the Diagnostic Worksheet regarding the conditions or location of the noise. This information can be used to duplicate the same conditions when you confirm the repair.

If the noise can be duplicated easily during the test drive, to help identify the source of the noise, try to duplicate the noise with the vehicle stopped by doing one or all of the following:

- 1) Close a door.
- 2) Tap or push/pull around the area where the noise appears to be coming from.
- 3) Rev the engine.
- Use a floor jack to recreate vehicle "twist".
- 5) At idle, apply engine load (electrical load, half-clutch on M/T model, drive position on CVT and A/T models).
- 6) Raise the vehicle on a hoist and hit a tire with a rubber hammer.
- Drive the vehicle and attempt to duplicate the conditions the customer states exist when the noise occurs.
- If it is difficult to duplicate the noise, drive the vehicle slowly on an undulating or rough road to stress the vehicle body.

CHECK RELATED SERVICE BULLETINS

After verifying the customer concern or symptom, check ASIST for Technical Service Bulletins (TSBs) related to that concern or symptom.

If a TSB relates to the symptom, follow the procedure to repair the noise.

LOCATE THE NOISE AND IDENTIFY THE ROOT CAUSE

- 1. Narrow down the noise to a general area. To help pinpoint the source of the noise, use a listening tool (Chassis Ear: J-39570, Engine Ear: J-39565 and mechanic's stethoscope).
- 2. Narrow down the noise to a more specific area and identify the cause of the noise by:
 - removing the components in the area that you suspect the noise is coming from.
 Do not use too much force when removing clips and fasteners, otherwise clips and fasteners can be broken or lost during the repair, resulting in the creation of new noise.
 - tapping or pushing/pulling the component that you suspect is causing the noise.
 Do not tap or push/pull the component with excessive force, otherwise the noise will be eliminated only temporarily.
 - feeling for a vibration with your hand by touching the component(s) that you suspect is (are) causing the
 noise.
 - placing a piece of paper between components that you suspect are causing the noise.
 - looking for loose components and contact marks.
 Refer to <u>GW-11</u>, "<u>Generic Squeak and Rattle Troubleshooting</u>".

REPAIR THE CAUSE

- If the cause is a loose component, tighten the component securely.
- If the cause is insufficient clearance between components:
- separate components by repositioning or loosening and retightening the component, if possible.
- insulate components with a suitable insulator such as urethane pads, foam blocks, felt cloth tape or urethane tape. A NISSAN Squeak and Rattle Kit (J-43980) is available through your authorized NISSAN Parts Department.

CAUTION:

Do not use excessive force as many components are constructed of plastic and may be damaged.

Always check with the Parts Department for the latest parts information.

The following materials are contained in the NISSAN Squeak and Rattle Kit (J-43980). Each item can be ordered separately as needed.

URETHANE PADS [1.5 mm (0.059 in) thick]

Insulates connectors, harness, etc.

76268-9E005: 100×135 mm (3.94×5.31 in)/76884-71L01: 60×85 mm (2.36×3.35 in)/76884-71L02: 15×25 mm (0.59×0.98 in)

INSULATOR (Foam blocks)

Insulates components from contact. Can be used to fill space behind a panel.

73982-9E000: 45 mm (1.77 in) thick, 50×50 mm (1.97×1.97 in)/73982-50Y00: 10 mm (0.39 in) thick, 50×50 mm (1.97×1.97 in)

INSULATOR (Light foam block)

80845-71L00: 30 mm (1.18 in) thick, 30×50 mm (1.18×1.97 in)

FELT CLOTH TAPE

Used to insulate where movement does not occur. Ideal for instrument panel applications.

68370-4B000: 15×25 mm (0.59×0.98 in) pad/68239-13E00: 5 mm (0.20 in) wide tape roll. The following materials not found in the kit can also be used to repair squeaks and rattles.

Revision: April 2013 EXT-10 2014 Versa Sedan

< SYMPTOM DIAGNOSIS >

UHMW (TEFLON) TAPE

Insulates where slight movement is present. Ideal for instrument panel applications.

SILICONE GREASE

Used instead of UHMW tape that will be visible or not fit.

Note: Will only last a few months.

SILICONE SPRAY

Use when grease cannot be applied.

DUCT TAPE

Use to eliminate movement.

CONFIRM THE REPAIR

Confirm that the cause of a noise is repaired by test driving the vehicle. Operate the vehicle under the same conditions as when the noise originally occurred. Refer to the notes on the Diagnostic Worksheet.

Generic Squeak and Rattle Troubleshooting

Refer to Table of Contents for specific component removal and installation information.

INSTRUMENT PANEL

Most incidents are caused by contact and movement between:

- 1. Cluster lid A and the instrument panel
- 2. Acrylic lens and combination meter housing
- 3. Instrument panel to front pillar finisher
- 4. Instrument panel to windshield
- Instrument panel pins
- 6. Wiring harnesses behind the combination meter
- A/C defroster duct and duct joint

These incidents can usually be located by tapping or moving the components to duplicate the noise or by pressing on the components while driving to stop the noise. Most of these incidents can be repaired by applying felt cloth tape or silicone spray (in hard to reach areas). Urethane pads can be used to insulate wiring harness.

CAUTION:

Do not use silicone spray to isolate a squeak or rattle. If you saturate the area with silicone, you will not be able to recheck the repair.

CENTER CONSOLE

Components to pay attention to include:

- 1. Shift selector assembly cover to finisher
- 2. A/C control unit and cluster lid C
- Wiring harnesses behind audio and A/C control unit

The instrument panel repair and isolation procedures also apply to the center console.

DOORS

Pay attention to the:

- 1. Finisher and inner panel making a slapping noise
- 2. Inside handle escutcheon to door finisher
- 3. Wiring harnesses tapping
- Door striker out of alignment causing a popping noise on starts and stops

Tapping or moving the components or pressing on them while driving to duplicate the conditions can isolate many of these incidents. You can usually insulate the areas with felt cloth tape or insulator foam blocks from the NISSAN Squeak and Rattle Kit (J-43980) to repair the noise.

TRUNK

Trunk noises are often caused by a loose jack or loose items put into the trunk by the owner. In addition look for:

- Trunk lid bumpers out of adjustment
- Trunk lid striker out of adjustment
- 3. The trunk lid torsion bars knocking together

EXT

J

Α

В

D

Е

Н

INFOID:0000000009268548

. .

M

N

 \circ

0

Р

Revision: April 2013 EXT-11 2014 Versa Sedan

< SYMPTOM DIAGNOSIS >

A loose license plate or bracket

Most of these incidents can be repaired by adjusting, securing or insulating the item(s) or component(s) causing the noise.

SUNROOF/HEADLINING

Noises in the sunroof/headlining area can often be traced to one of the following:

- Sunroof lid, rail, linkage or seals making a rattle or light knocking noise
- Sun visor shaft shaking in the holder
- 3. Front or rear windshield touching headlining and squeaking

Again, pressing on the components to stop the noise while duplicating the conditions can isolate most of these incidents. Repairs usually consist of insulating with felt cloth tape.

OVERHEAD CONSOLE (FRONT AND REAR)

Overhead console noises are often caused by the console panel clips not being engaged correctly. Most of these incidents are repaired by pushing up on the console at the clip locations until the clips engage. In addition look for:

- 1. Loose harness or harness connectors.
- 2. Front console map/reading lamp lens loose.
- 3. Loose screws at console attachment points.

SEATS

When isolating seat noise it's important to note the position the seat is in and the load placed on the seat when the noise is present. These conditions should be duplicated when verifying and isolating the cause of the noise.

Cause of seat noise include:

- Headrest rods and holder
- A squeak between the seat pad cushion and frame
- The rear seatback lock and bracket

These noises can be isolated by moving or pressing on the suspected components while duplicating the conditions under which the noise occurs. Most of these incidents can be repaired by repositioning the component or applying urethane tape to the contact area.

UNDERHOOD

Some interior noise may be caused by components under the hood or on the engine wall. The noise is then transmitted into the passenger compartment.

Causes of transmitted underhood noise include:

- 1. Any component installed to the engine wall
- Components that pass through the engine wall
- 3. Engine wall mounts and connectors
- 4. Loose radiator installation pins
- Hood bumpers out of adjustment
- Hood striker out of adjustment

These noises can be difficult to isolate since they cannot be reached from the interior of the vehicle. The best method is to secure, move or insulate one component at a time and test drive the vehicle. Also, engine rpm or load can be changed to isolate the noise. Repairs can usually be made by moving, adjusting, securing, or insulating the component causing the noise.

< SYMPTOM DIAGNOSIS >

Diagnostic Worksheet

INFOID:0000000009268549


Dear Customer:


We are concerned about your satisfaction with your vehicle. Repairing a squeak or rattle sometimes can be very difficult. To help us fix your vehicle right the first time, please take a moment to note the area of the vehicle where the squeak or rattle occurs and under what conditions. You may be asked to take a test drive with a service advisor or technician to ensure we confirm the noise you are hearing.


SQUEAK & RATTLE DIAGNOSTIC WORKSHEET


I. WHERE DOES THE NOISE COME FROM? (circle the area of the vehicle)

The illustrations are for reference only, and may not reflect the actual configuration of your vehicle.









Continue to page 2 of the worksheet and briefly describe the location of the noise or rattle. In addition, please indicate the conditions which are present when the noise occurs.

-1-

LAIA0072E

Р

Revision: April 2013 EXT-13 2014 Versa Sedan

F

Α

В

D

Е

G

Н

1

J

EXT

Ν

0

II. WHEN DOES IT OCCUR? (please check to Anytime 1 st time in the morning Only when it is cold outside	_	apply)	
Only when it is hot outside	☐ Dry or dust☐ Other: IV. WHAT TYF		t E
Over rough roads Over speed bumps Only about mph On acceleration Coming to a stop On turns: left, right or either (circle) With passengers or cargo Other: After driving miles or minutes	□ Squeak (like tennis shoes on a clean floor) □ Creak (like walking on an old wooden floor) □ Rattle (like shaking a baby rattle) □ Knock (like a knock at the door) □ Tick (like a clock second hand) □ Thump (heavy muffled knock noise) □ Buzz (like a bumble bee)		
TO BE COMPLETED BY DEALERSHIP PER: Test Drive Notes:	SONNEL	NO	Initials of person
Vehicle test driven with customer			performing
Noise verified on test drive Noise source located and repaired	pair		
- Follow up test drive performed to confirm re	_	_	


This form must be attached to Work Order

LAIA0071E

REMOVAL AND INSTALLATION

FRONT BUMPER

Exploded View



- 1. Front bumper side bracket (RH)
- 4. Front bumper fascia finisher (RH) (If equipped)
- 7. Tow cover

- . Front bumper reinforcement
- Front bumper fascia

5.

- 3. License plate bracket
- 3. Front bumper energy absorber
- 6. Fog lamp finisher (RH) (if equipped)
- 9. Under cover

EXT

J

Α

В

C

D

Е

F

Н

INFOID:0000000009268550

M

Ν

0

Р

Revision: April 2013 EXT-15 2014 Versa Sedan

FRONT BUMPER

< REMOVAL AND INSTALLATION >

- 10. Fog lamp finisher (LH) (if equipped)
- 11. Front bumper fascia finisher (LH) 12. Front bumper side bracket (LH) (if equipped)

13. Front spoiler

Spring nut

B. Screw grommet

(Pawl

Removal and Installation


INFOID:0000000009268551

REMOVAL


CAUTION:

Bumper fascia is made of resin. Do not apply strong force to it, and be careful to prevent contact with

- 1. Open hood.
- Remove front bumper fascia upper side clips (A).



- 3. Remove under cover. Refer to EXT-19, "Removal and Installation".
- 4. Remove fender protector clips and screws to access bumper fascia screw. Refer to EXT-26, "Removal and Installation".
- Remove front bumper fascia screws (A) (LH/RH). 5.




- 6. Remove front bumper fascia lower side clips and screws.
- 7. Pull front bumper fascia away as shown by the arrows in the illustration and then disengage front bumper fascia from front bumper side brackets (LH/RH).



CAUTION:

When removing front bumper fascia, two people are required to avoid damaging.



- 8. Disconnect the harness connectors from the front fog lamps (LH/RH) (If equipped).
- Remove front bumper fascia.
- 10. Remove the following parts after removing front bumper fascia.
 - Front bumper side brackets (LH/RH)
 - Fog lamp finishers (LH/RH) (If equipped)

FRONT BUMPER

< REMOVAL AND INSTALLATION >


- Fog lamps (LH/RH) (If equipped). Refer to EXL-105, "Removal and Installation".
- Front grille. Refer to EXT-23, "Removal and Installation".
- License plate bracket
- 11. Remove front bumper energy absorber.
- 12. Remove nuts and front bumper reinforcement.

INSTALLATION

Installation is in the reverse order of removal.

NOTE:

- The following table shows the specified values for checking normal installation specifications.
- · Fitting adjustment cannot be performed.



Portion		Clearance	Surface height difference
Front bumper – Hood	A – A	2.5 – 6.3 mm (0.10 – 0.25 in)	(-1.45) - (+2.45) mm [(-0.057) - (+0.096) in]
Front bumper – Headlamp	B – B	0.1 – 4.2 mm (0.004 – 0.17 in)	_
	C – C	0.1 – 3.9 mm (0.004 – 0.15 in)	0.1 – 3.9 mm (0.004 – 0.15 in)
Front bumper – Front fender	D – D	0.0 – 1.0 mm (0.000 – 0.04 in)	(-0.3) - (+1.7) mm [(-0.01) - (+0.07) in]

EXT

Α

В

C

D

Е

IVI

Ν


0

Р

Revision: April 2013 EXT-17 2014 Versa Sedan

UNDER COVER

Exploded View



- 1. Front bumper side bracket (RH)
- 4. Front bumper fascia finisher (RH) 5. (If equipped)
- 7. Tow cover
- 10. Fog lamp finisher (LH) (if equipped)
- . Front bumper reinforcement
- 5. Front bumper fascia
- 8. License plate bracket
- Front bumper fascia finisher (LH) (if equipped)
- 3. Front bumper energy absorber
- 6. Fog lamp finisher (RH) (if equipped)
- 9. Under cover
- Front bumper fascia finisher (LH) 12. Front bumper side bracket (LH)