

MODEL All  
with rain/light sensor

Shown on model 166



P67.10-2407-03

**i** For the complaint "*Random wiping of windshield wiper*" because of faulty bonding of the window positions in the area of the rain/light sensor (see picture), the damage code 67001 19 (cosmetic fault) is to be used when replacing the windshield.

	Remove, install windshield		AR67.10-P-1000RT
--	----------------------------	--	------------------

MODEL 202 as of 1.6.97,  
208,  
210 as of 1.3.97,  
210.081 /281

<b>i</b>	The rear window defroster diagnosis is described in <b>general networking (GVN)</b>		
A 7.1 □ 11	General networking (GVN) diagnosis previous knowledge		AD00.19-P-2000A
A 7.1 □ 12c	General networking (GVN) diagnosis, functional checking, rear window defroster actual values		AD00.19-P-3002A
A 7.1 □ 12d	General networking (GVN) diagnosis, functional checking, actual values		AD00.19-P-3003A
A 7.1 □ 13c	General networking (GVN) diagnosis, fault memory, rear window defroster		AD00.19-P-4002A
A 7.1 □ 14c	General networking (GVN) diagnosis, troubleshooting plan, rear window defroster		AD00.19-P-5002A
A 7.1 □ 20	General networking (GVN) electrical testing		AD00.19-P-6000A