

9. Remove pop rivets (22) and spring (21) .




Illustration 12

g02949378

Note: Mark the location of needle bearings (23) for assembly procedure.

10. Remove needle bearings (23) .

Assembly Procedure

Table 1

Required Tools			
Tool	Part Number	Part Description	Qty
A	7M-7456	Bearing Mount Compound	1




Illustration 13

g02949378

1. Install needle bearings (23) .