Disassembly and Assembly 3046 Engine For Caterpillar Built Machines

Media Number -SENR6458-05

Publication Date -01/04/2004

Date Updated -22/04/2004

i01020755

Air Inlet Manifold - Install

SMCS - 1058-012

Installation Procedure

NOTICE

Keep all parts clean from contaminants.

Contaminants may cause rapid wear and shortened component life.




Illustration 1

g00523540

Note: Check condition of the inlet manifold gasket. If the gasket is damaged, use a new part for replacement.

1. Install the gasket and air inlet manifold (11).