



JIC Diagram (High Pressure Details)

RWC12791

JIC HIGH PRESSURE CIRCUITS DIAGRAM

Tractor represented is a QUAD-RANGE equipped 4450 with hydraulically assisted mechanical sensed rockshaft and two SCV's. Valves and flow are shown with number two SCV in use. Rockshaft is in neutral.

Legend for High Pressure JIC Diagram

- A—Lubrication Pressure Oil**
- B—Charge-Return Pressure Oil**
- C—Transmission Control Pressure Oil**
- D—High Pressure Oil**
- E—Trapped Oil**

70U;270005 MX2 120887